

Metering Services, Inc.

Quotation

Servicing Backflows & Meters in AZ for 30 years.

515 S. 48th St. Suite 108
 Tempe, AZ 85281
 Phone (480) 894-0200 Fax (480) 731-4793

DATE 10/11/2016
 Quotation # 470

Quotation For:	SERVICE ADDRESS	MAILING ADDRESS (if different)
Name	Christi Merrill	
Company Name	Canon School District	
Street Address	PO Box 89	
City, ST ZIP	Black Canyon City, AZ 85324	
Phone		
email	purchasing@canon50.com	

Description of Work:

Two bf devices failed during annual backflow certification; SN 625086 needs to be replaced; SN 296084 will need a complete rebuild kit (this quote does not include a Black Canyon City permit fee)

QUANTITY	DESCRIPTION	UNIT PRICE	AMOUNT
1	8" Wilkins 375ASTR OS&Y LF BF Assy	\$7,085.79	7,085.79
2	8" x 18" Spools	\$244.01	488.02
1	Nuts, Bolts, Gaskets	\$90.00	90.00
1	Crane Truck	\$240.00	240.00
1	Labor - 2-man crew	\$960.00	960.00
1	2" Watts 909M2QT Comp. Reb. Kit	\$295.86	295.86
	(tech will not charge labor for this repair)		
2	Backflow Certification Fee	N/C	

Quotation valid until: 10/21/2016

Prepared by: Gina Lallak

SUBTOTAL	\$	9,159.67
OTHER		-
TOTAL	\$	9,159.67

The above information is not an invoice & is only an estimate of the services described.

This estimate is valid for 10 days unless it may be revised due to any of the following conditions:

- a) request for changes and/or additions to original work quoted
- b) increase in material cost
- c) further work or materials are required due to unforeseen circumstances during job
- d) error when quotation was prepared.

When you are ready to schedule the work or if you have any questions, please
 Contact: Gina Lallak, 480-894-0200, gina@msiaz.net

A signature & 50% downpayment is required to begin work. Cash, Check, Visa, Mastercard, or Discover accepted.

THANK YOU FOR YOUR BUSINESS!

Approved: _____ Date: _____



Metering Services, Inc.
 515 South 48th Street, Tempe, Arizona 85281
"Assuring You a Safe Water Supply"
 (480) 894-0200 Fax: (480) 731-4793 (800) 279-3122

**Backflow Prevention
 Assembly Test Report**
 Control # 2010689

Water Purveyor Black Canyon Water Improvement		Assembly Address 34630 S School Loop RD		
Permit No	Mfr WATTS	Size 8"	Model Number 909M1	Serial Number 625086
Facility/Owner Canon School District		Phone (623) 374-5588	Meter No Fireline	
Address 34630 S School Loop RD		City, State, Zip Black Canyon City AZ 85324		
Contact Christi Merrill		Contact Phone (623) 374-5588		
Address PO BOX 89		<input checked="" type="checkbox"/> Containment <input type="checkbox"/> Isolation	<input type="checkbox"/> New <input checked="" type="checkbox"/> Existing	<input type="checkbox"/> Replacement Old Serial:
On-Site Location Next to Driveway W Side of School				<input checked="" type="checkbox"/> Domestic <input checked="" type="checkbox"/> Fire <input type="checkbox"/> Irrigation
Reduced Pressure Principle Assembly				<input type="checkbox"/> Back Pressure
Double Check Valve Assembly			<input type="checkbox"/> USC 10th Edit.	Line Pressure:
	Check Valve #1	Check Valve #2	Differential Pressure Relief Valve	Pressure Vacuum Breaker
Initial Test	<input type="checkbox"/> Closed Tight <input checked="" type="checkbox"/> RP <u>NA</u> PSID <input type="checkbox"/> DC <input type="checkbox"/> Leaked	<input type="checkbox"/> Closed Tight DC _____ PSID <input type="checkbox"/> Leaked	Opened at _____ PSID <input type="checkbox"/> Leaked <input checked="" type="checkbox"/> Did Not Open	Air Inlet Opened at _____ PSID <input type="checkbox"/> Leaked <input type="checkbox"/> Did not Open
R E P A I R S	<input type="checkbox"/> CLEANED REPLACED <input type="checkbox"/> Rubber Kit <input type="checkbox"/> Other	<input type="checkbox"/> CLEANED REPLACED <input type="checkbox"/> Rubber Kit <input type="checkbox"/> Other	<input type="checkbox"/> CLEANED REPLACED <input type="checkbox"/> Rubber Kit <input type="checkbox"/> Other	Check Held at _____ PSID <input type="checkbox"/> Leaked
	<input type="checkbox"/> CLEANED REPLACED <input type="checkbox"/> Rubber Kit <input type="checkbox"/> Other	<input type="checkbox"/> CLEANED REPLACED <input type="checkbox"/> Rubber Kit <input type="checkbox"/> Other	<input type="checkbox"/> CLEANED REPLACED <input type="checkbox"/> Rubber Kit <input type="checkbox"/> Other	<input type="checkbox"/> CLEANED REPLACED <input type="checkbox"/> Rubber Kit <input type="checkbox"/> Other
Final Test	<input type="checkbox"/> Closed Tight <input type="checkbox"/> RP _____ PSID <input type="checkbox"/> DC	<input type="checkbox"/> Closed Tight DC _____ PSID	Opened at _____ PSID	Air Inlet _____ PSID CK Valve _____ PSID

THE ABOVE REPORT IS CERTIFIED TO BE TRUE:

MSVS

Initial Test By [Signature] Certified Tester No **03-02241** Date 10-06-16 Pass Fail

Repair By _____ Test Kit Serial No **15286033**

Final Test By _____ Certified Tester No _____ Pass Fail

Comments: Recommend Replacing. (78.5")



Metering Services, Inc.
 515 South 48th Street, Tempe, Arizona 85281
"Assuring You a Safe Water Supply"
 (480) 894-0200 Fax: (480) 731-4793 (800) 279-3122

**Backflow Prevention
 Assembly Test Report**
 Control # 2010690

Water Purveyor Black Canyon Water Improvement		Assembly Address 34630 S School Loop RD		
Permit No	Mfr WATTS	Size 2"	Model Number 009M2QT	Serial Number 296084
Facility/Owner Canon School District		Phone (623) 374-5588	Meter No 31886516	
Address 34630 S School Loop RD		City, State, Zip Black Canyon City AZ 85324		
Contact Christi Merrill		Contact Phone (623) 374-5588		
Address PO BOX 89		<input checked="" type="checkbox"/> Containment <input type="checkbox"/> Isolation	<input type="checkbox"/> New <input checked="" type="checkbox"/> Existing	<input type="checkbox"/> Replacement Old Serial:
On-Site Location At Meter E Side of School				<input checked="" type="checkbox"/> Domestic <input type="checkbox"/> Fire <input checked="" type="checkbox"/> Irrigation
Reduced Pressure Principle Assembly				<input type="checkbox"/> Back Pressure
Double Check Valve Assembly				<input type="checkbox"/> USC 10th Edit. Line Pressure:
	Check Valve #1	Check Valve #2	Differential Pressure Relief Valve	Pressure Vacuum Breaker
Initial Test	<input type="checkbox"/> Closed Tight <input type="checkbox"/> RP _____ PSID <input type="checkbox"/> DC <input checked="" type="checkbox"/> Leaked	<input type="checkbox"/> Closed Tight DC _____ PSID <input type="checkbox"/> Leaked	Opened at _____ PSID <input checked="" type="checkbox"/> Leaked <input type="checkbox"/> Did Not Open	Air Inlet Opened at _____ PSID <input type="checkbox"/> Leaked <input type="checkbox"/> Did not Open
REPAIRS	<input type="checkbox"/> CLEANED REPLACED <input type="checkbox"/> Rubber Kit <input type="checkbox"/> Other	<input type="checkbox"/> CLEANED REPLACED <input type="checkbox"/> Rubber Kit <input type="checkbox"/> Other	<input type="checkbox"/> CLEANED REPLACED <input type="checkbox"/> Rubber Kit <input type="checkbox"/> Other	Check Held at _____ PSID <input type="checkbox"/> Leaked <input type="checkbox"/> CLEANED REPLACED <input type="checkbox"/> Rubber Kit <input type="checkbox"/> Other
Final Test	<input type="checkbox"/> Closed Tight <input type="checkbox"/> RP _____ PSID <input type="checkbox"/> DC	<input type="checkbox"/> Closed Tight DC _____ PSID	Opened at _____ PSID	Air Inlet _____ PSID CK Valve _____ PSID

THE ABOVE REPORT IS CERTIFIED TO BE TRUE:

MSVS

Initial Test By *M. Merrill* Certified Tester No **03-02241** Date *10-6-16* Pass Fail
 Repair By _____ Test Kit Serial No **15286033**
 Final Test By _____ Certified Tester No _____ Pass Fail

Comments: *(Found off, left off) #1 Check Broken
 Rebuild kit recommended.*