## PARKING LOT RESTORATION **FOR** PISTOR MIDDLE SCHOOL TUCSON UNIFIED SCHOOL DISTRICT TUCSON, AZ

ENGINEER'S NOTES

THE CONTRACTOR.

IN-KIND.

CONSTRUCTION SURVEY & STAKING IS THE RESPONSIBILITY OF

EXISTING OR NEWLY DAMAGED AND/OR DISPLACED CONCRETE CURB, GUTTER, SIDEWALK, OR DRIVEWAY SLAB SHALL BE

REPAIRED OR REPLACED, BEFORE FINAL ACCEPTANCE OF THE

AS NECESSARY TO ENSURE SURFACE FINISHES, SUCH AS RIPRAP, DECOMPOSED GRANITE, TURF. ETC. MEET FINISH

EXISTING LANDSCAPE IRRIGATION LINES & APPURTENANCES

UNDERGROUND UTILITIES OF RECORD ARE SHOWN AS

ACCURATELY AS POSSIBLE. LOCATIONS ARE BASED ON FIELD

AND INFORMATION PROVIDED BY TUSD FORCES. ENGINEER

ASSUMES NO RESPONSIBILITY FOR IMPROPER LOCATIONS OR FAILURE TO SHOW UTILITY LOCATIONS ON CONSTRUCTION PLANS.

THE CONTRACTOR SHALL VERIFY HORIZONTAL AND VERTICAL LOCATION OF ALL UTILITIES PRIOR TO ANY CONSTRUCTION AND

ASSUMES FULL RESPONSIBILITY FOR ANY DAMAGE AND/OR REPAIR THERETO. CALL BLUESTAKE 1-800-782-5348 TWO

FOR PAVEMENT DESIGN INFORMATION, REFER TO THE PAVEMENT

DESIGN REPORT PREPARED FOR THIS PROJECT BY SMITH &


ANNALA ENGINEERING, CO, (SAECO), DATED JUNE 24, 2022,


FULL WORKING DAYS PRIOR TO EXCAVATION.

PROJECT NUMBER 29.22.2409.


SURVEYS OF VISIBLE PEDESTALS, TRANSFORMERS, METER BOXES,

## SITE HILDRETH (PUBLIC) ARDINAL (PUBLIC) **IMPROVEMENTS**





PISTOR MIDDLE SCHOOL 5455 SOUTH CARDINAL AVENUE TUCSON, AZ 85746



TUSD BONDS and ARCHITECTURE

SHEET: C1.0 SCALE: AS SHOWN AR ZONA811. Call 811 or click Arizona811.com PAGE 1 OF 5

OWNER: TUCSON UNIFIED SCHOOL DISTRICT 1010 E. TENTH ST. TUCSON, AZ 85719 P. 520.225.6000 www.tusd1.org 177 N. CHURCH AVENUE SUITE 1000 TUCSON, AZ 85701 P. 520.495.4065 www.dibblecorp.com RESTORATION SCHOOL MIDDLE LOCATION MAP A PORTION OF THE SOUTHWEST 1/4 OF SECTION 04, TOWNSHIP 15 SOUTH, RANGE 13 EAST G&SRM, PIMA COUNTY, ARIZONA 3" = 1 MILELONG: -111° 01' 40.36" W 018110.

