

Site Assessment: Need for Speed Bumps in Front Bus Drive Lane at DeGrazia Elementary School

DeGrazia Elementary School
5051 W. Overton Rd.
Tucson, AZ 85742

The current layout and traffic patterns at DeGrazia Elementary School clearly indicate the need for speed bumps in the front bus drive to improve student and staff safety. The bus route cuts across the main parking lot and runs directly in front of the campus entrance. The loop's slight leftward curve further limits drivers' visibility, increasing the risk of accidents as buses approach the crossing.

MUSD's recommendation to install asphalt speed bumps is a proactive measure to address these safety concerns. By slowing bus traffic, speed bumps will provide drivers with additional reaction time and ensure that students and staff can cross the drop-off area more safely.

Jack Romaker

Project Manager

J.E.Romaker@maranausd.org

Phone: 520.682.4707 Ext 2701

Cell: 520.909.7946

Facilities Management

Marana Unified School District

11249 W. Grier Road

Marana, AZ 85653