Climatec, LLC 2851 W Kathleen Rd Phoenix, AZ, 85053 Telephone: 602-906-4151

Email: Phxservice@climatec.com

 TO:
 ALHAMBRA SCHOOL DISTRICT #68
 DATE:
 8/22/2017

 RE: SITE:
 SIMPSON
 PROJECT:
 SN#N1207060558

 ATTN:
 Sam Garcia / 602-336-2982 /
 PROPOSAL #
 61111

General Description

ALHAMBRA- Simpson SN#N1207060558

Quote request per Sam Garcia

Climatec proposes to replacement the existing 3" Febco 825YD Domestic backflow assembly Serial Number #N1207060558 attached to water meter #17558541 located on the East side of the School along the sidewalk. This unit has been repaired multiple times in the past and is an older assembly that is no longer being manufactured, that is in poor condition. Suggest replacing this assembly with a new Febco 860 assembly due to poor condition and age.

Note; this replacement will require 3 technicians. new assembly weight 233 lbs.

Major Systems

Parts

Quantity	<u>Description</u>	Unit Price	Discount %	Extended Price
1.00	Febco: 3" LF860 NRS #0122933 *Lead Free* Reduced Pressure Zone Assembly	\$3,828.38	25.00	\$2,871.29
3.00	3" Nut, bolt & gasket kit	\$18.98	25.00	\$42.71
Parts Sub Total:			\$2,913.99	

Additional Services

Quantity	<u>Description</u>	<u>Unit Price</u>	Extended Price
1.00	City of Phoenix backflow replacement permit	\$150.00	\$112.50

Additional Services Sub Total:

\$112.50

ı	а	h	റ	r

Clarifications

<u>Hours</u>	<u>Description</u>	<u>Unit Price</u>	Extended Price
16.0	Labor Charge	\$85.00	\$1,360.00

Labor Sub Total:

\$1,360.00 **\$4,386.49**

Grand Total:

This proposal is based on the terms and agreement of the 1GPA program

- 1) All work to be completed during regular business hours Monday through Friday 8am to 5pm.
- 2) This replacement will require shutting off the Domestic water supply for 2 to 3 hours.
- 3) Retest this assembly after it is replacede and send an updated report to the water purveyor.
- 4) Additional repairs or damaged pipe, fittings, valves, etc. discovered during the above scope not included in this price.
- 5) Does not include a City water shut down for the replacement of this assembly if needed.



Climatec, LLC 2851 W Kathleen Rd Phoenix, AZ, 85053 Telephone: 602-906-4151 Email: Phxservice@climatec.com

Exclusions

Sales Tax, Additional materials needed outside of the scope of work.

Climatec, LLC		Customer	
Submitted By:		Approved By:	
Gordon Collins	8/22/2017		
Name:	Date:	Name:	Date:
Gordon Collins	8/22/2017		
Signature:	Date:	Signature:	Date:
Title:		Title:	