Validation Form SFBADJW-16

Submission ID: 3889 **Current Status:** Resubmitted 10/21/2024 11:12:26 AM

Initial Submission Date: 8/20/2024 **Resubmission Date:** 10/21/2024

District Name: Phoenix Union High School District

Contact Person: Alan Hubbard **Contact Phone:** 6022180690

Contact Email: hubbard@phoenixunion.org

School: District Support Facility

Site Address: 2526 West Osborn

Phoenix, AZ 85017

Project Title: PUHSD – District Support Facility – Main Building

Project Detail: This project scope of work is to construct a new 3-story administration with 1-story

service building

attached. The new administration building will consist of new restrooms, offices,

conference rooms,

training room, staff lounge, and transportation management operations. The new

service building

will consist of restrooms, automotive equipment, automotive materials, and all

necessary items for

district transportation vehicles to be repaired.

Site work will consist of an all-new parking lot for staff and new parking lot for bus

parking, new site

lighting, primary power delivery, rehabilitated asphalt on all existing fire-lane

pathways, new

propane fueling and new vehicle fueling systems. Additionally, there will be new

underground site

utilities including domestic water, sewer, and storm drain along with landscape

beautification

throughout the development.

Offsite utilities

onsite new asphalt and repair seal coat

Project Date Range: 7/21/2022 TO 9/30/2024

\$17,622,548.00 **Total Project Cost: Adjacent Ways Cost:** \$950,637.00

Board Meeting Date:

Validation Status: Review Pending

Staff Analysis: 10/21/24 documentation is in order I need to have the Total Amount: adjusted to the

full total amount.

10/7/2024 Looking at the drawing we still need to have an updated proposal and that

of the SFD schedule of values

There are some corrections that need to be made. The bus parking lanes are just like parking lots, it is not dropping off the students. Please have this revised so that we can have it approved. Please have the REV to the updated documents when attaching, this would be the SFD SOV from the contractor's proposal and the color overlay to be corrected. I also see that no striping and signage is broken out. If you

PDF Generated: 10/21/2024 11:12:27 AM **Submission ID:** 3889 Page: 1

| have any questions please reach out. |
|--------------------------------------|
| |

Board Decision:

PDF Generated: 10/21/2024 11:12:27 AM **Submission ID:** 3889 **Page:** 2