



5009 E Washington

Phoenix, AZ 85009

M: (602) 558-0187 O: (602) 560-3535

tgould@weemasphalt.com

Field Elementary

Asphalt Repairs
 2325 E Adobe St.
 Mesa, AZ 85213

Date: 8/28/2025

Estimator: Trevor Gould

	Adjacent Ways - Remove And Replace Asphalt With 3"
	Non Adjacent Ways - Remove And Replace Asphalt With 3"
	Speed Hump Replacement
	Speed Bump Replacement

NOTE: ABOVE DIMENSIONS ARE AN ESTIMATE. NOT DRAWN TO SCALE



5009 E Washington
Phoenix, AZ 85009

M: (602) 558-0187 O: (602) 560-3535

tgould@weemasphalt.com

Field Elementary

Asphalt Maintenance

2325 E Adobe St.
Mesa, AZ 85213

Date: 8/28/2025

Estimator: Trevor Gould

	Adjacent Ways - Crack Seal, Sealcoat (PMM) and Restripe
	Non Adjacent Ways - Crack Seal, Sealcoat (PMM) and Restripe

NOTE: ABOVE DIMENSIONS ARE AN ESTIMATE. NOT DRAWN TO SCALE